


LanTEK III Software Update Notice -

Version 3.117 must be installed before updating to version 3.200 or higher. Installing 3.200 from a version earlier than 3.117 will cause the remote handset update to fail.


First “downgrade” both handsets to 3.117, then upgrade back to version 3.200.

LanTEK will always install the newest file from the USB flash drive. Follow this procedure to install an older software version from a USB flash drive containing multiple software files.


1. Copy LT2_3_117.IDL to the USB flash drive. Containing the 3.200 software file.




2. Right-click on LT2_3_200.IDL and select Rename.



3. Change the extension of the LT2_3_200.IDL file to BAK and press Enter.




4. Click Yes on the warning message.






5. LanTEK will ignore the file with the BAK extension and install version 3.117 during the update.




6. Place the flash drive into the LanTEK and follow the installation procedure on the next page.

After the installation is complete resume with step 7 below.

7. After installing version 3.117 on the Main and Remote LanTEK handsets, delete the LT2_3_117.IDL file from the flash drive.




8. With only the LT2_3_200.IDL file on the flash drive, update the Main and Remote LanTEK handsets to version 3.200.





LanTEK III Software Update Procedure

Main Handset



Remote Handset

